Oil Field Environmental Incident Summary

Responsible Party: CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: THERESA 1-20

Field Name: CEDAR HILLS Well File #: 13922

Date Incident:1/18/2015Time Incident:08:00Facility ID Number:County:BOWMANTwp:132Rng:106Sec:20Qtr:

Location Description:

Submitted By: Timothy Ilse Received By:

Contact Person: Timothy Ilse

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units	
Oil	16	Barrels	16	Barrels	16	barrels	
Brine	19	Barrels	19	Barrels	19	barrels	

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: 12/28/2016 Clean Up Concluded: 1/25/2015

Risk Evaluation:

None

Areal Extent:

100 ft. by 50 ft.

Potential Environmental Impacts:

Well site soil

Action Taken or Planned:

Fluid was sucked up and contaminated material was removed and placed in a lined pit and covered on location.

Wastes Disposal Location: PertoComp

Agencies Involved: Called NDIC @ 6:42 p.m.

Updates

Date: 1/20/2015 Status: Reviewed - Assigned to Other Agency Author: Washek, Sandi

Updated Oil Volume: 16.00 barrels

Updated Salt Water Volume: 16.00 barrels

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the report, all material remained on site of the well pad. NDIC retains oversight.